enough for wire nut to pass through and must be serviced from rear. front, on other models the hole in the oven liner is not large into excisting wiring. On some models sensor may be serviced from Use two (2) ceremic wire mute contained in this package to splice