
167082, 184178, 607468, 623143, 642239


EN Replacing 167082 drain pump with 642239

9-vane drain pump 167082 is no longer available, having been replaced by 642239. Using connector housing 623143 allows dishwasher wire harnesses to connect to the replacement 642239 drain pump. Please follow the instructions below to assemble connector housing 623143 to dishwasher wire harnesses and to plug the harnesses into the replacement 642239 drain pump.


Push each of the two (2) spade terminals into the white, plastic connector housing, making sure they're fully seated into the connector housing.



When finished, the connector will look like this:



Firmly push the connector into the drain pump terminal until the spade terminals are fully seated.



The same procedure is used to adapt 4-vane replacement drain pump 607468 to replace 4-vane drain pump 184178. These pumps are used in Washington State in homes with Johnson Tee fittings.